



Hyundai Motor America
10500 Talbert Avenue, Fountain Valley, CA 92708
TEL: 714-965-3000 FAX: 714-965-3816
WEB: Hyundai.com

June 3, 2025

To: Collision Repair Industry

POSITION STATEMENT: Pre-Repair and Post-Repair System Scanning

Hyundai vehicles are equipped with multiple electronic components and systems within each vehicle. Therefore, it is important that vehicles involved in a collision have a pre-repair scan and a post-repair scan so that repairers are aware of any diagnostic trouble codes that may be present, regardless if a warning light or malfunction indicator light is illuminated.

A pre-repair scan will alert the repairer to diagnostic trouble codes or items that may be malfunctioning within the vehicle. This aids the repairer to develop more accurate repair estimates prior to beginning repairs. The post-repair system scan provides confirmation that systems are functioning properly and calibrated.

Hyundai Motor America requires a pre-repair scan to ensure safe and accurate repairs and also a post-repair scan to ensure all systems and components are functioning, calibrated, and communicating properly with **NO** diagnostic trouble codes present.

Hyundai values customer safety and requires the collision industry follow the guidelines above for completing pre-repair and post-repair scans to achieve safe and quality repairs.